



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE72TLO

ISUZU N75 190

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	26/10/2022	VIN	JAANPR75MM7101027	Rear Suspension	Steel
Year	2022	Body Style	Box Van	Rear Doors	Roller
Mileage	92,243 Km Not Warranted	Cab Type	DAY CAB	Tail Lift	Column
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	WHITE	Axle Combi	4x2		



OUTSTANDING RECALL, WARNING LIGHTS ON DASH

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm

2: Bonnet
Chipped
Multiple Chips



3: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint

4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Roof
Cracked
Replace

8: Qtr Panel nsr
Cracked
Replace




9: Qtr Panel nsr
Dented
With Paint Damage

10: Door osf
Scratched
Over 25mm Thru Paint



11: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

12: Moulding osf Wing
Scratched (Painted)
UpTo 25mm Thru Paint



13: Bumper Front
Scratched
Over 100mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault