

VEHICLE INSPECTION REPORT



Ford Transit Custom 300 2.0 ECOBLUE 130PS

Inspection	Veh	nicle	
Serious Damage? No		- Plu	s VAT
	V5	Buy	yer To Apply

Details

Reg. date	30/06/2019	VIN	WF0YXXTTGYJG84462	CAP Below	£6,450.00
Year	2019	Body Style	Panel Van SWB	Gearbox	MANUAL
Mileage	80,490 Miles Not	MOT Due	Expired	Gears	6
	Warranted	CAP Clean	£9,175.00		
Fuel Type	Diesel	CAP Average	£8.075.00		
Colour	SILVER				

AD-BLUE, SIDE LOAD DOOR, ROOF RACK, E/MIRRORS, HEATED SEATS, HEATED WINDSCREEN

Tyres	
Tyres NSF	
NSR	
OSF OSR	
Spare	


Features

- Bluetooth connection
- Rear parking sensor
- Passenger airbag
- Cruise control
- Front electric windows
- Central locking
- Front parking sensor
- Metallic Paint
 Cloth seat trim
- · Park assist camera
- Drivers airbag

Photos




Commercial Vehicle Auctions Limited





Condition Check



Damage Photos





1: Bonnet Chipped Multiple Chips

2: Bumper Front Scratched Over 100mm Thru Paint





3: Wing nsf Scratched Over 25mm Thru Paint

4: Door nsf Scratched Over 25mm Thru Paint



5: Door nsf Scratched Over 25mm Thru Paint



6: Door nsf Scratched Over 25mm Thru Paint



7: Door Moulding nsf Missing Replace



8: Qtr Panel nsr Scratched Over 25mm Thru Paint



9: Qtr Panel nsr Scratched Over 25mm Thru Paint



11: Door nsr Dented Over 30mm



13: Door nsr Dented Over 30mm



10: Qtr Panel nsr Scratched Over 25mm Thru Paint



12: Door nsr Dented Over 30mm



14: Door osr Dented Over 30mm



15: Door osr Dented Over 30mm



16: Bumper Rear Moulding Broken Replace



17: Lamp osr Broken Replace



18: Qtr Panel osr Dented Over 30mm



19: Door osf Scratched Over 25mm Thru Paint



20: Door Moulding nsf Missing Replace





21: Door Pad osf Soiled Heavy

22: Seat Base Cover osf Torn Over 3mm



23: Seat Base Cover nsf Soiled Heavy

Interior

Carpet Condition Seat Condition	OK Poor		Upholstery Condition Odour	Poor -	
EML light illuminated		OK	Oil warning light illumina	ated	ОК
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light ill	uminated	OK