

VEHICLE INSPECTION REPORT

PF70DZW

Fiat Ducato 35 2.3 Multijet 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 04/01/2021

VIN ZFA25000002P65147

CAP Below £3,150.00

Year 2021

Body Style Dropside MWB

Gearbox MANUAL

Mileage 141,178 Miles
Warranted

MOT Due Expired

Gears 6

CAP Clean £4,150.00

Tail Lift Column

Fuel Type Diesel

CAP Average £3,775.00

Colour WHITE

WARNING LIGHT ON DASH *HAVE TO STALL TO STOP ENGINE RUNNING* AD-BLUE, E/ MIRRORS, TOW BAR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Dented
Over 30mm



3: Fascia Panel
Missing
Replace



4: Carpets Front
Holed
Over 3mm



5:

Interior

Carpets Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	-
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK