



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PE17JHX**

## VOLVO FM 370

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Present

### Details

Reg. date	08/05/2017	Colour	WHITE	Gearbox	AUTOMATIC
Year	2017	VIN	YV2X922C4HB806520	Axle Combi	6x2
Mileage	543,169 Km Not Warranted	Body Style	Curtainside	Tail Lift	Cantilever
Fuel Type	Diesel	Cab Type	GLOBETROTTER CAB		

### SURROUND CAMERA SYSTEM

### Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Park assist camera
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Broken  
Replace



2: Fog Lamp Surround is  
Scratched (Painted)  
Over 25mm Not Thru Paint



3: Screen Front  
Chipped  
Over 10mm

4: Bumper Front Moulding  
Broken  
Replace



5: Fog Lamp Surrounds  
Scratched (Painted)  
Over 25mm Not Thru Paint

6: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm



7: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm

8: Door osf  
Scratched  
Over 25mm Not Thru Paint



9: Door osf  
 Chipped  
 Edge Chip

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK