



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DF13URP

Mercedes-Benz Actros 1842

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details		Colour	Cab Type
Reg. date	27/08/2013	WHITE	SLEEPER CAB
Year	2013	VIN	WDB9634032L783268
Mileage	1,822,317 Km Warranted	Body Style	Tractor Unit
Fuel Type	Diesel	MOT Due	30/04/2026
		Axle Combi	4x2
		Rear Suspension	Air

SLIDING 5TH WHEEL.

Tyres	NSI1	NSI2	NSI3	NSI4
NSF	OSI1	OSI2	OSI3	OSI4
OSF	NSO1	NSO2	NSO3	NSO4
Spare	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Air conditioning

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Door Moulding of
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Cracked
Replace

4: Wing nsf
Dented
With Paint Damage



5: Door osf
Dented
With Paint Damage



6: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel Moulding ns
Broken
Replace

8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: B Post ns
Cracked
Replace

10: B Post ns
Dented
With Paint Damage



11: Door nsf
Dented
With Paint Damage

12: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK