



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DG16JXL

Mercedes-Benz Sprinter 516 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details		Fuel Type	Diesel	Body Style	Minibus
Reg. date	11/04/2016	Colour	WHITE	MOT Due	09/10/2026
Year	2016	VIN	WDB906652P253266	Gearbox	AUTOMATIC
Mileage	65,813 Miles Warranted				

15 SEATER, WHEELCHAIR LIFT



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint

2: Wing of
Scratched
Up To 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Wing nsf
Dented
With Paint Damage



7: Wing nsf
Scratched
Over 25mm Thru Paint

8: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm




9: Sill ns
Rusted
Over 5mm

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel nsr
Rusted
Over 5mm

12: Qtr Panel nsr
Rusted
Over 5mm



13: Qtr Panel nsr
Dented
Over 30mm

14: Qtr Panel nsr
Dented
Over 30mm



15: Qtr Panel osr
Rusted
Over 5mm

16: Door osf
Dented
Between 10mm + 30mm



17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault