



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DG16JXM

Mercedes-Benz Sprinter 516 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details		Fuel Type	Body Style
Reg. date	11/04/2016	Diesel	Minibus
Year	2016	Colour	WHITE
Mileage	83,004 Miles Warranted	VIN	WDB9066552P257501
		MOT Due	03/01/2027
		Gearbox	AUTOMATIC

15 SEATER, WHEELCHAIR LIFT

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
Multiple Chips



3: Grille Front
Broken
Replace

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Door nsf
Dented
With Paint Damage



7: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Dented
Over 30% Of Panel

10: Qtr Panel nsr
Dented
Over 30% Of Panel



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

12: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



13: Qtr Panel osr
Dented
With Paint Damage

14: Qtr Panel osr
Rusted
Over 5mm



15: Qtr Panel osr
Dented
With Paint Damage

16: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



17: Door osf
Dented
With Paint Damage

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK