



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**EY19LSU**

## Mercedes-Benz Sprinter 514 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details		Fuel Type	Body Style
Reg. date	05/04/2019	Diesel	Minibus
Year	2019	Colour	WHITE
Mileage	40,503 Miles Warranted	VIN	WDB9066572P639472
		MOT Due	23/09/2026
		Gearbox	AUTOMATIC

\*WARNING LIGHT ON DASH\* \*TAIL LIFT IN-OP\* 15 SEATER, SIDE LOADING DOOR, WHEELCHAIR LIFT




Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features


- Park assist camera
- Front electric windows

## Photos





## Condition Check



## Damage Photos



1: Wing of  
Dented  
With Paint Damage

2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front Moulding  
Broken  
Replace

4: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



5: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm

6: Qtr Panel Arch Extension os  
Broken  
Replace



7: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm

8: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



9: Qtr Panel osr  
Rusted  
Over 5mm

10: B Post os  
Rusted  
Over 5mm



11: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm

12: Door osf  
Dented  
Over 2 UpTo 10mm

**Interior**

**Carpet Condition**  
**Seat Condition**

OK  
OK

**Upholstery Condition**  
**Odour**

OK  
-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK