



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**CN61DFU**

## Mercedes-Benz Sprinter 513 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details		Fuel Type		Body Style	
Reg. date	12/10/2011	Diesel		Minibus	
Year	2011	Colour	WHITE	MOT Due	11/07/2026
Mileage	111,860 Miles Warranted	VIN	WDB906652S586609	Gearbox	AUTOMATIC

\*WARNING LIGHT ON DASH\* 15 SEATER



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features


- Park assist camera
- Front electric windows

## Photos






## Condition Check



## Damage Photos



1: Headlamp os  
Broken  
Replace

2: Wing osf  
Dented  
Over 30mm



3: Panel Front  
Dented  
With Paint Damage

4: Bumper Front  
Cracked  
Over 25mm



5: Bonnet  
Chipped  
Multiple Chips

6: Screen Front  
Chipped  
Over 10mm



7: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm

8: Panel Front  
Dented  
With Paint Damage



9: Wing nsf  
Dented  
With Paint Damage

10: Door nsf  
Dented  
With Paint Damage



11: Door Moulding nsf  
Scuffed (Unpainted)  
Over 100mm

12: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



13: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm

14: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



15: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm

16: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



17: Wing osf  
Scratched  
Over 25mm Not Thru Paint

**Interior**

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK