



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PO13ECJ

Daf LF 45.140

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Reg. date	09/04/2013	VIN	XLRAE45FF0L425358	Gearbox	MANUAL
Year	2013	Body Style	Box Van	Axle Combi	4x2
Mileage	881,977 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	Service documents	Printout	Tail Lift	Cantilever
Colour	RED	MOT Due	Expired		

COLLECTED AS NON-RUNNER, CAB CORROSION, TAIL LIFT PLATFORMS, FAULTS NEED ATTENDTION, WARNING LIGHTS ON DASH

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD

Photos





Condition Check




Damage Photos



1: Sill os
Rusted
Over 5mm

2: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
Multiple Chips

4: Wing osf
Scratched
Over 25mm Not Thru Paint



5: Door osf
Dented
With Paint Damage

6: Qtr Panel osr
Rusted
Over 5mm



7: Tailgate
Rusted
Over 5mm

8: Qtr Panel nsr
Rusted
Over 5mm



9: Door Moulding nsf
 Scuffed (Unpainted)
 Over 100mm

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK