



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | [cva.noreply@cva-auctions.co.uk](mailto:cva.noreply@cva-auctions.co.uk)

# VEHICLE INSPECTION REPORT

**CU65CKD**

## FORD TRANSIT 350 2.2 TDCI 155PS ECONETIC

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	17/02/2016	VIN	WF0XXXTTGXFM07422	CAP Below	£1,900.00
Year	2016	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	128,493 Miles Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£3,225.00		
Colour	WHITE	CAP Average	£2,650.00		

AD-BLUE, SIDE LOAD DOOR, TOW BAR, E/ MIRRORS, HEATED WINDSCREEN, RACKING IN REAR, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

## Features


- Bluetooth connection
- Park assist camera
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Carpets Front  
Holed  
Over 3mm

2: Seat Base Cover of  
Holed  
Over 3mm



3: Rear Panel Trim Int  
Holed  
Over 3mm

4: Bonnet  
Chipped  
Multiple Chips



5: Bumper Front  
Hole  
Over 25mm

6: Wing nsf  
Dented  
With Paint Damage



7: Bumper Front Moulding  
Scratched (Painted)  
Over 25mm Thru Paint

8: Wing nsf  
Scratched  
Over 25mm Thru Paint



9: A Post ns  
Chipped  
Multiple Chips

10: Door Mirror Assy nsf  
Broken  
Replace



11: Door nsf  
Scratched  
Over 25mm Thru Paint

12: Door nsf  
Dented  
With Paint Damage



13: Qtr Panel nsr  
Dented  
With Paint Damage

14: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



15: Bumper Rear  
Scratched  
Over 100mm Thru Paint

16: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



17: Door nsr  
Scratched  
Over 25mm Thru Paint

18: Door osr  
Chipped  
Multiple Chips



19: Bumper Rear  
Scratched  
Over 100mm Thru Paint

20: Qtr Panel osr  
Dented  
With Paint Damage



21: Qtr Panel Moulding os  
Broken  
Replace

22: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



23: Door osf  
Scratched  
Over 25mm Thru Paint

24: Wing osf  
Chipped  
Multiple Chips



25: Door Moulding osf  
Scratched (Painted)  
Over 25mm Thru Paint

26: A Post os  
Chipped  
Over 5mm



27: Bumper Front  
 Scratched  
 Over 100mm Thru Paint

28: Bumper Front Moulding  
 Scratched (Painted)  
 Over 25mm Thru Paint

**Interior**

**Carpet Condition**

Poor

**Seat Condition**

Poor

**Upholstery Condition**

OK

**Odour**

-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		