



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SN13BVL

Daf LF 55.250

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details			
Reg. date	01/08/2013	Colour	YELLOW
Year	2013	VIN	XLRAE55GF0L425344
Mileage	238,646 Miles Warranted	Body Style	Hotbox
Fuel Type	Diesel	MOT Due	30/04/2026
		Gearbox	MANUAL
		Axle Combi	4x2
		Rear Suspension	Steel

WARNING LIGHT ON DASH ECON BODY, REAR VIEW CAMERA.

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD


Photos






Type Approval No. e11*2007/004/001		AE190206202 25000	
Manufacturer/Model DAF FA LF55		Speedometer N	
Function RIGID	Year of Original Registration 01/08/13	Year of Manufacture 2013	
(1) Description of Weights Applicable to vehicle	(2) Weights not to be exceeded in the British Isles	(3) Design weight (allow 10% margin in excess of (2))	(4) Date of issue
Gross Weight (See note 1)	18000	19000	DEPARTMENT FOR TRANSPORT GREAT BRITAIN REPLACEMENT
Train Weight (See note 2)	21500	22500	
Max. Train Weight (See note 3)			
Axle Weights (See note 4)	Axle 1 7500		
	Axle 2 11500		
	Axle 3		
	Axle 4		

NOTES
1. A loadable gross weight and/or axle weight shall also apply to a loadable gross weight and/or axle weight for any intermediate axle.
2. The MAXIMUM permissible axle weight for any intermediate axle shall be 10% in excess of the design weight.
3. The MAXIMUM permissible axle weight for any intermediate axle shall be 10% in excess of the design weight.
4. The MAXIMUM permissible axle weight for any intermediate axle shall be 10% in excess of the design weight.





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Door Moulding of
Scuffed (Unpainted)
Over 100mm



3: Wing of
Scratched
Over 25mm Thru Paint

4: Door of
Dented
Over 30mm



5: Qtr Panel of
Rusted
Over 5mm

6: Tailgate
Rusted
Over 5mm



7: Qtr Panel of
Rusted
Over 5mm

8: B Post of
Rusted
Over 5mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK