



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DA13RYU

Mercedes-Benz Actros 1842

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	27/08/2013	Colour	WHITE	Cab Type	SLEEPER CAB
Year	2013	VIN	WDB9634032L782398	Gearbox	AUTOMATIC
Mileage	1,755,539 Km Warranted	Body Style	Tractor Unit	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/04/2026	Rear Suspension	Air


CENTRE AIR DUCT MISSING SLIDING 5TH WHEEL.


Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Wing of
Scratched
Over 25mm Thru Paint



3: Door osf
Dented
Over 30mm

4: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel osr
Poor Previous Repair
Paint Flake

6: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel Trim os
Missing
Replace

8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel Moulding nsf
Broken
Replace

10: Door nsf
Dented
With Paint Damage



11: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK