



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HK65KJF

TOYOTA HILUX INVINCIBLE 3.0 D-4D 171PS

Non Runner

| Inspection | | Vehicle | |
|-----------------|----|---------|----------------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | Buyer To Apply |

| Details | | | | | |
|-----------|-------------|-------------|-------------------|------------|-----------|
| Reg. date | 13/01/2016 | VIN | AHTFZ29G409138814 | CAP Below | £4,775.00 |
| Year | 2016 | Body Style | Pickup Double Cab | Gearbox | AUTOMATIC |
| Mileage | Not Showing | MOT Due | Expired | Gears | 5 |
| Fuel Type | Diesel | CAP Clean | £8,075.00 | Axle Combi | 4x4 |
| Colour | BLACK | CAP Average | £6,600.00 | | |


NON-RUNNER, NO KEYS, FRONT BUMPER PARTS MISSING, CRACKED WINDSCREEN, CRACKED ALLOY, TYRE OFF RIM AD-BLUE, TOW BAR, E/ MIRRORS, HEATED WINDSCREEN, MOT SHOWS 119,342 MILES 23/01/2025




| | |
|-------|--|
| Tyres | |
| NSF | |
| NSR | |
| OSF | |
| OSR | |
| Spare | |

Features

- Navigation system
- Leather seat trim
- Rear parking sensor
- Air conditioning
- Front electric windows


Photos








Condition Check



Damage Photos



1: Bumper Front Grill
Missing
Replace

2: Bonnet
Dented
With Paint Damage



3: Bonnet
Scratched
Over 25mm Thru Paint

4: Screen Front
Cracked
Replace



5: Bumper Front
Missing
Replace

6: Wing Front Arch Extension ns
Broken
Replace



7: Wing nsf
Dented
With Paint Damage

8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door Mirror Assy nsf
Broken
Replace

10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Damaged
Replace

12: Door osr
Dented
With Paint Damage



13: Bumper Rear
Dented
Over 30% Of Panel

14: Qtr Panel osr
Poor Previous Repair
Rippled Over 30%



15: Qtr Panel osr
Dented
With Paint Damage

16: Door osr
Dented
With Paint Damage



17: Door osf
Dented
With Paint Damage

18: Door Mirror Assy osf
Broken
Replace



19: Wing osf
Dented
With Paint Damage

20: Wheel osr
Damaged
Replace



21: Wheel of
Damaged
Replace

22: B Post of
Dented
Over 30mm



23: Moulding of Wing
Broken
Replace

24: Bumper Front
Hole
Over 25mm



25: General Interior
Soiled
Light

26: In Car Entertainment
Broken
Replace

