



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CU64FHO

Ford Transit 350 2.2 TDCi 125ps H2 Van

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	28/10/2014	VIN	WF0XXTTGXEU33641	CAP Below	£1,575.00
Year	2014	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	125,547 Miles Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£2,900.00		
Colour	WHITE	CAP Average	£2,300.00		

POWER STEERING INOP, INPUT ERROR ON MOT MILEAGE SIDE LOAD DOOR, TOW BAR, ROOF RACK, E/MIRRORS, DEADLOCKS, INVERTER, LADDER STOW, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door nsf
Dented
With Paint Damage

4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Chipped
Multiple Chips

6: Fuel Flap
Missing
Replace



7: Door Moulding nsf
Missing
Replace

8: Qtr Panel nsr
Chipped
Multiple Chips



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage

12: Qtr Panel nsr
Dented
Over 30mm




13: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Qtr Panel Moulding ns
Missing
Replace

16: Qtr Panel nsr
Dented
With Paint Damage



17: Qtr Panel nsr
Dented
With Paint Damage

18: C Post ns
Dented
With Paint Damage



19: Qtr Panel osr
Dented
Over 30mm

20: Qtr Panel osr
Dented
With Paint Damage



21: Qtr Panel osr
Scratched
Over 25mm Thru Paint

22: Qtr Panel osr
Dented
With Paint Damage





23: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

24: Qtr Panel osr
Dented
Over 30mm



25: Qtr Panel osr
Dented
Over 30mm

26: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



27: Qtr Panel osr
Scratched
Over 25mm Thru Paint

28: Door osf
Scratched
Over 25mm Thru Paint



29: Door osf
Scratched
Over 25mm Thru Paint

30: Wing osf
Dented
Over 30mm



31: Bumper Front
Scratched
Over 100mm Thru Paint

32: Wing nsf
Dented
Over 30mm




33: Screen Front
Chipped
UpTo 10mm

34: Fascia Panel
Missing
Replace




35: Fascia Panel
Missing
Replace

36: Door Pad osf
Soiled
Heavy



37: Seat Base Cover osf
Soiled
Heavy

38: Seat Back Cover osf
Soiled
Heavy



39: Seat Back Cover nsf
Soiled
Heavy

40: Seat Base Cover nsf
Soiled
Heavy



41: Door Pad nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		
		Steering	Fault