



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CU13EHB

Ford Transit T350 TDCi 125ps

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details			
Reg. date	15/05/2013	VIN	WF0XXTTFXBP32350
Year	2013	Body Style	Panel Van LWB
Mileage	127,639 Miles Warranted	MOT Due	Expired
Fuel Type	Diesel	CAP Clean	£1,750.00
Colour	WHITE	CAP Average	£1,375.00
		CAP Below	£920.00
		Gearbox	MANUAL
		Gears	6

SIDE LOAD DOOR, TOW BAR, ROOF RACK, INVERTER, LADDER STOW, DEADLOCKS, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES


Tyres
NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos






FORD			
e1*2007/46*0239		*WFOXXXTTFXBP32350*	
CYRA		3500	kg
0.53		6000	kg
4CP	B	1850	kg
3G	R	2250	kg
AA	N		
M6			
W(mm)		L(mm)	a(mm)
W 3750		FAC6	



Condition Check



Damage Photos



1: Roof
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Missing
Replace

4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Bumper Front
Scratched
Over 100mm Thru Paint

6: Panel Front
Missing
Replace



7: Wing nsf
Dented
With Paint Damage

8: Wing nsf
Rusted
Over 5mm



9: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

10: Wing nsf
Rusted
Over 5mm



11: Door nsf
Dented
With Paint Damage

12: Sill ns
Rusted
Over 5mm



13: B Post ns
Rusted
Over 5mm

14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Qtr Panel nsr
Dented
With Paint Damage

16: Qtr Panel nsr
Dented
With Paint Damage



17: Qtr Panel nsr
Dented
With Paint Damage

18: Qtr Panel nsr
Dented
With Paint Damage



19: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

20: C Post ns
Scratched
Over 25mm Thru Paint




21: Qtr Panel Moulding ns
Broken
Replace

22: Qtr Panel osr
Chipped
Multiple Chips



23: Qtr Panel osr
Dented
Over 30% Of Panel

24: Sill os
Rusted
Over 5mm



25: Qtr Panel osr
Dented
With Paint Damage

26: Qtr Panel osr
Scratched
Over 25mm Thru Paint



27: B Post os
Rusted
Over 5mm

28: Door osf
Dented
Over 30mm



29: Door osf
Chipped
Multiple Chips

30: Wing osf
Rusted
Over 5mm



31: Door Mirror Assy osf
Broken
Replace

32: Wing osf
Rusted
Over 5mm



33: Screen Front
Cracked
Replace

34: Carpets Front
Holed
Over 3mm



35: Fascia Panel
Missing
Replace

36: Fascia Panel
Missing
Replace



37: Seat Base Cover of
Soiled
Heavy

38: Door Pad of
Soiled
Heavy



39: Seat Base Cover nsf
Soiled
Heavy

40: Door Pad nsf
Soiled
Heavy



41: Fascia Panel
Broken
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		