



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CU65EOY

Ford Transit 350 2.2 TDCi 155ps

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	22/02/2016	VIN	WF0XXXTTGXFM07432	CAP Below	£2,000.00
Year	2016	Body Style	Panel Van MWB	Gearbox	MANUAL
Mileage	118,541 Miles Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£3,375.00		
Colour	WHITE	CAP Average	£2,750.00		

SIDE LOAD DOOR, TOW BAR, DEADLOCKS, INVERTER, LADDER STOW, V5 NEW KEEPER DOCUMENT
REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES


Tyres
NSF
NSR
OSF
OSR
Spare


Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Missing
Replace

4: Panel Front
Scratched
Over 25mm Thru Paint



5: Wing nsf
Chipped
Multiple Chips

6: Door nsf
Chipped
Multiple Chips



7: Door nsf
Dented
With Paint Damage

8: Door nsf
Dented
Over 30mm



9: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

10: Door Moulding nsf
Missing
Replace



11: Qtr Panel nsr
Chipped
Multiple Chips

12: Qtr Panel nsr
Dented
Over 30mm



13: Qtr Panel nsr
Dented
With Paint Damage

14: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



15: Qtr Panel nsr
Dented
Over 30mm

16: Qtr Panel nsr
Dented
With Paint Damage



17: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

18: Qtr Panel nsr
Dented
With Paint Damage



19: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

20: C Post ns
Dented
With Paint Damage



21: Door nsr
Dented
With Paint Damage

22: Door osr
Dented
Over 30% Of Panel



23: Qtr Panel osr
Dented
With Paint Damage

24: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



25: Qtr Panel osr
Dented
Over 30mm

26: Door osf
Dented
Over 30mm



27: Door osf
Dented
Over 30mm

28: Door Moulding osf
Broken
Replace




29: Door osf
Chipped
Multiple Chips

30: Wing osf
Chipped
Multiple Chips



31: Screen Front
Scratched
Over 30mm

32: Carpets Front
Soiled
Heavy



33: Door Pad osf
Soiled
Heavy

34: Seat Base Cover osf
Torn
Over 3mm



35: Door Pad nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		