



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20TDZ

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

| | | | | | |
|-----------|---------------------------|-------------|-------------------|-----------|------------|
| Reg. date | 31/07/2020 | VIN | W1V9106332P251275 | CAP Below | £10,700.00 |
| Year | 2020 | Body Style | Panel Van L2 | Gearbox | AUTOMATIC |
| Mileage | 56,030 Miles Warranted | MOT Due | 18/10/2026 | Gears | 9 |
| Fuel Type | Diesel | CAP Clean | £15,300.00 | | |
| Colour | WHITE | CAP Average | £13,450.00 | | |

AD-BLUE, SIDE LOADING DOOR

Tyres


| |
|-------|
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Flasher Side Repeater os
Broken
Replace

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Wing nsf
Scratched
Over 25mm Thru Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Moulding nsf Wing
Missing
Replace

6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

8: Door nsf
Dented
With Paint Damage



9: Sill ns
Dented
Between 10mm + 30mm

10: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel nsr
Dented
With Paint Damage

12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

14: Qtr Panel Moulding ns
Scuffed (Unpainted)
UpTo 100mm



15: Door nsr
Dented
Between 10mm + 30mm

16: Door nsr
Scratched
Over 25mm Not Thru Paint



17: Door nsr
Dented
Over 30mm

18: Door nsr
Chipped
Edge Chip



19: Door osr
Chipped
Edge Chip

20: Qtr Panel osr
Dented
With Paint Damage



21: Qtr Panel osr
Scratched
Over 25mm Thru Paint

22: Qtr Panel osr
Scratched
Over 25mm Thru Paint



23: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

24: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



25: Sill os
Dented
With Paint Damage

26: Door osf
Chipped
Edge Chip



27: Qtr Panel osr
Dented
With Paint Damage

28: Carpets Front
Holed
Over 3mm



29: Carpets Front
Holed
Over 3mm

30: Seat Base Cover osf
Holed
Over 3mm

Interior

| Carpet Condition | Average | Upholstery Condition | Average |
|--------------------------|---------|--|---------|
| Seat Condition | Average | Odour | No |
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |