



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20TCU

Mercedes-Benz Sprinter 314 CDI

| Inspection | | Vehicle | |
|-----------------|----|---------|-----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | To Follow |

| Details | | | | | |
|-----------|---------------------------|-------------|-------------------|-----------|------------|
| Reg. date | 31/07/2020 | VIN | W1V9106332P251468 | CAP Below | £10,100.00 |
| Year | 2020 | Body Style | Panel Van L2 | Gearbox | AUTOMATIC |
| Mileage | 66,663 Miles Warranted | MOT Due | 07/08/2026 | Gears | 9 |
| Fuel Type | Diesel | CAP Clean | £14,400.00 | | |
| Colour | WHITE | CAP Average | £12,650.00 | | |

AD-BLUE, SIDE LOADING DOOR



| |
|-------|
| Tyres |
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Features


- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Sill ns
Dented
With Paint Damage

6: Door nsr
Dented
With Paint Damage



7: Door nsr
Scratched
Over 25mm Not Thru Paint

8: Sill ns
Dented
With Paint Damage



9: Qtr Panel Moulding ns
Broken
Replace

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
Over 30mm

12: Qtr Panel Trim ns
Scuffed
Over 25mm



13: Door osr
Dented
With Paint Damage

14: Badgedecal Rear
Missing
Replace



15: Door osr
Chipped
Edge Chip

16: Door nsr
Chipped
Edge Chip



17: Door osr
Dented
Over 30mm

18: Qtr Panel osr
Dented
Over 30mm



19: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

20: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



21: Qtr Panel osr
Scratched
Over 25mm Thru Paint

22: Qtr Panel osr
Dented
Over 30mm



23: Qtr Panel osr
Dented
Over 30mm

24: Qtr Panel osr
Scratched
Over 25mm Thru Paint



25: Door osf
Chipped
Edge Chip

26: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



27: Carpets Front
 Holed
 Over 3mm

28: Seat Base Cover of
 Holed
 Over 3mm

Interior

| Carpet Condition | Average | | Upholstery Condition | Average |
|--------------------------|---------|----|--|---------|
| Seat Condition | Average | | Odour | No |
| Engine Runs | | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | | OK | Clutch Slip Test from Static | OK |
| Parking Brake | | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | | No Excessive Smoking | OK |
| EML light illuminated | | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | | OK | DPF light illuminated | OK |
| ABS light illuminated | | OK | Service indicator light illuminated | OK |