

VEHICLE INSPECTION REPORT

YF71VHD

Mercedes-Benz Sprinter 315 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/02/2022

Year 2022

Mileage 142,113 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P430176

Body Style Panel Van LWB

MOT Due 26/03/2026

CAP Clean £11,400.00

CAP Average £10,550.00

CAP Below £9,125.00

Gearbox MANUAL

WARNING LIGHT ON DASH AD-BLUE, SIDE LOAD DOOR, DEADLOCKS (NO KEYS)

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Wing nsf
Dented
Over 30mm



4: Qtr Panel nsr
Dented
Over 30mm



5: Qtr Panel nsr
Dented
Over 30mm



6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel nsr
Dented
Over 30mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
Over 30mm



11: Lamp nsr
Broken
Replace



12: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



13: Badgedecal Rear
Broken
Replace



14: Door nsr
Scratched
Over 25mm Thru Paint



15: Door osr
Dented
Over 30mm



16: Door osr
Dented
Over 30mm



17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



19: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



20: Qtr Panel osr
Dented
Over 30mm



21: Qtr Panel osr
Dented
Over 30mm



22: Qtr Panel osr
Scratched
Over 25mm Thru Paint



23: Qtr Panel osr
Dented
Over 30mm



24: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



25: Wing osf
Dented
Over 30mm



26: Carpets Front
Holed
Over 3mm



27: Seat Base Cover osf
Torn
Over 3mm



28: Seat Base Cover nsf
Soiled
Heavy



29: Screen Front
Chipped
Over 10mm



30: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	Fault	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK		