

VEHICLE INSPECTION REPORT

YF71VHL

Mercedes-Benz Sprinter 315 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/02/2022

Year 2022

Mileage 108,462 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P427651

Body Style Panel Van LWB

MOT Due 13/02/2026

CAP Clean £12,800.00

CAP Average £11,900.00

CAP Below £10,250.00

Gearbox MANUAL

*ENGINE NOISE**FRONT O/S WING DAMAGE & DOOR INOP* AD-BLUE, SIDE LOAD DOOR, DEADLOCKS (WITH KEYS)

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Rusted
Over 5mm



2: Bumper Front
Cracked
Over 25mm



3: Wing nsf
Dented
Over 30mm



4: Wing nsf
Rusted
Over 5mm



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel nsr
Dented
Over 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
Over 30mm



9: Qtr Panel nsr
Dented
Over 30mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Qtr Panel Moulding ns
Broken
Replace



13: Qtr Panel nsr
Dented
Over 30mm



14: Door nsr
Dented
Over 30mm



15: Badgedecal Rear
Broken
Replace



16: Door osr
Dented
Over 30mm



17: Door osr
Dented
Over 30mm



18: Bumper Rear Moulding
Broken
Replace



19: Lamp osr
Broken
Replace



20: Qtr Panel osr
Dented
Over 30mm



21: Qtr Panel osr
Dented
Over 30mm



22: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



23: Qtr Panel osr
Dented
Over 30mm



24: Qtr Panel osr
Dented
Over 30mm



25: Door osf
Dented
Over 30mm



26: Wing osf
Dented
Over 30mm



27: Door Moulding osf
Missing
Replace




28: Door Mirror Assy osf
Broken
Replace



29: Carpets Front
Holed
Over 3mm



30: Door Pad osf
Soiled
Heavy



31: Seat Base Cover osf
Holed
Over 3mm



32:



33: Screen Front
Chipped
Over 10mm



34: Door Pad nsf
Soiled
Heavy



35: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK