



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HD19NTN

Land Rover Discovery 3.0 SDV6 306 HSE

| Inspection | | Vehicle | |
|-----------------|----|---------|----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | Present |

| Details | | | |
|-----------|----------------------------|-------------|-------------------|
| Reg. date | 07/06/2019 | VIN | SALRACAK1K2406682 |
| Year | 2019 | Body Style | SUV |
| Mileage | 76,325 Miles Not Warranted | MOT Due | 08/07/2026 |
| Fuel Type | Diesel | CAP Clean | £18,900.00 |
| Colour | SILVER | CAP Average | £16,300.00 |
| | | CAP Below | £12,700.00 |
| | | Gearbox | AUTOMATIC |
| | | Gears | 8 |
| | | Axle Combi | 4x4 |

WARNING LIGHTS ON DASH KEYLESS IGNITION, E/ MIRRORS

| |
|-------|
| Tyres |
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Features


- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Chipped
Multiple Chips




3: Screen Front
Cracked
Replace

4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Door osr
Scratched
Up To 25mm Thru Paint

6: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



7: Seat Belt nsr
Broken
Replace

8: Other
N/A
N/A



9: Dash Warning Lights
 Displayed
 No Action

Interior

| | | | | |
|-------------------------|---------|----|-----------------------------|----|
| Carpet Condition | Average | | Upholstery Condition | OK |
| Seat Condition | OK | | Odour | - |
| Engine Runs | | OK | No Excessive Smoking | OK |
| Brakes | | OK | | |
| Parking Brake | | OK | | |
| EML light illuminated | | OK | DPF light illuminated | OK |