



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20BNY

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	30/06/2020	VIN	W1V9076352P251695	CAP Below	£3,300.00
Year	2020	Body Style	Panel Van L3	Gearbox	AUTOMATIC
Mileage	288,812 Miles Warranted	MOT Due	23/02/2027	Gears	6
Fuel Type	Diesel	CAP Clean	£4,725.00		
Colour	WHITE	CAP Average	£4,100.00		

AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS



Tyres
NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Fuel Flap
Dented
Over 30% Of Panel



3: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



4: Qtr Panel nsr
Dented
With Paint Damage



5: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Dented
Over 30mm

10: Qtr Panel nsr
Dented
Over 30mm



11: Qtr Panel nsr
Dented
With Paint Damage

12: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



13: Qtr Panel nsr
Dented
With Paint Damage

14: Qtr Panel nsr
Dented
With Paint Damage



15: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



16: Door nsr
Dented
Over 30mm



17: Door nsr
Dented
Over 30mm



18: Badgedecal Rear
Missing
Replace



19: Door osr
Dented
Over 30mm



20: Door osr
Dented
Over 30mm



21: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



22: Qtr Panel osr
Dented
With Paint Damage



23: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



24: Qtr Panel osr
Dented
With Paint Damage



25: Qtr Panel osr
Dented
With Paint Damage



26: Qtr Panel osr
Dented
Over 30mm



27: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

28: Qtr Panel osr
Dented
With Paint Damage



29: Qtr Panel osr
Dented
Over 30mm

30: Qtr Panel osr
Dented
With Paint Damage



31: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

32: Door osf
Dented
With Paint Damage



33: Door osf
Dented
With Paint Damage

34: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



35: Wing osf
Dented
With Paint Damage

36: A Post osf
Dented
With Paint Damage



37: Door Pad osf
Soiled
Heavy

38: Seat Base Cover osf
Torn
Over 3mm



39: Seat Base Cover nsf
Soiled
Heavy

40: Seat Back Cover nsf
Soiled
Heavy

Interior

Carpet Condition

OK

Upholstery Condition

Poor

Seat Condition

Poor

Odour

No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		