



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20NEN

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details

Reg. date	22/07/2020	VIN	W1V9076352P252410	CAP Below	£4,450.00
Year	2020	Body Style	Panel Van LWB	Gearbox	AUTOMATIC
Mileage	229,550 Miles Warranted	MOT Due	25/07/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£6,350.00		
Colour	WHITE	CAP Average	£5,525.00		

SIDE LOAD DOOR.


Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Rear parking sensor
- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm

2: Seat Base Cover of
Missing
Replace



3: Sill os
Rusted
Over 5mm

4: Bonnet
Dented
With Paint Damage



5: Wing osf
Dented
With Paint Damage

6: Door osf
Dented
With Paint Damage



7: Qtr Panel osr
Dented
With Paint Damage

8: Sill os
Dented
With Paint Damage



9: Tailgate
Dented
With Paint Damage

10: Badgedecal Rear
Broken
Replace



11: Qtr Panel nsr
Dented
With Paint Damage

12: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



13: Sill ns
Dented
With Paint Damage

14: Door nsr
Dented
With Paint Damage



15: Door nsf
Dented
With Paint Damage

16: Wing nsf
Dented
With Paint Damage



17: Roof
Rusted
Over 5mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Poor	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK