



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20KUH

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details

Reg. date	20/07/2020	VIN	W1V9076352P250423	CAP Below	£6,150.00
Year	2020	Body Style	Panel Van LWB	Gearbox	AUTOMATIC
Mileage	140,452 Miles Warranted	MOT Due	25/07/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£8,750.00		
Colour	WHITE	CAP Average	£7,675.00		

SIDE LOAD DOOR.


Tyres



NSF
NSR
OSF
OSR
Spare

Features


- Rear parking sensor
- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm

2: Seat Base Cover of
Missing
Replace



3: Sill os
Rusted
Over 5mm

4: Bonnet
Dented
With Paint Damage



5: Bumper Front Moulding
Broken
Replace

6: Door osf
Dented
Over 30mm



7: Qtr Panel osr
Dented
With Paint Damage

8: Tailgate
Dented
With Paint Damage



9: Badgedecal Rear
Broken
Replace

10: Qtr Panel nsr
Dented
With Paint Damage



11: Door nsr
Dented
With Paint Damage

12: Door Moulding nsr
Broken
Replace



13: Door nsf
Dented
With Paint Damage

14: Flasher Side Repeater ns
Missing
Replace



15: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK