



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**DY68DHC**

## Vauxhall Vivaro 2700 1.6 CDTI 120PS SPORTIVE

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	06/09/2018	VIN	W0VF7G602JV655082	CAP Below	£3,075.00
Year	2018	Body Style	Panel Van L1	Gearbox	MANUAL
Mileage	121,735 Miles Not Warranted	MOT Due	12/05/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£4,750.00		
Colour	BLACK	CAP Average	£4,050.00		

\*POOR STARTER, WARNING LIGHTS ON DASH\* AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS


Tyres
NSF
NSR
OSF
OSR
Spare

## Features

- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Radio/CD
- Passenger airbag


## Photos







## Condition Check



## Damage Photos



1: Door Mirror Assy osf  
Broken  
Replace

2: Bumper Front  
Insecure  
Action Required



3: Bonnet  
Chipped  
Multiple Chips

4: Bumper Front  
Scratched  
Over 100mm Thru Paint



5: Bumper Front  
Chipped  
Multiple Chips

6: Bumper Front  
Scratched  
25 to 100mm Thru Paint



7: Bumper Front Moulding  
Scuffed (Unpainted)  
Up To 100mm

8: Door Mirror Assy nsf  
Broken  
Replace



9: Door nsf  
Scratched  
Over 25mm Thru Paint

10: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



11: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

12: Qtr Panel Moulding ns  
Missing  
Replace



13: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

14: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



15: Door osf  
 Scratched  
 Over 25mm Thru Paint

16: Door Mirror Glass os  
 Broken  
 Replace



17: Seat Base Cover nsf  
 Soiled  
 Heavy

18: Dash Warning Lights  
 Displayed  
 No Action

**Interior**

**Carpet Condition**  
**Seat Condition**

OK  
 Poor

**Upholstery Condition**  
**Odour**

OK  
 No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault