

VEHICLE INSPECTION REPORT



Daf LF LF 180


| Inspection | | Vehicle | | | | |
|-----------------|----------------------|--------------|--------------|------|-----------------|--------|
| Serious Damage? | No | VAT Plus VAT | | | | |
| | | V5 | Buyer To App | bly | _ | |
| Details | | | | | | |
| Reg. date | 22/10/2020 | Body Style | Box Van | | Axle Combi | 4x2 |
| Year | 2020 | Cab Type | DAY CAB | | Rear Suspension | Steel |
| Mileage | 229,806 Km Warranted | Gearbox | auto | | Rear Doors | Roller |
| Fuel Type | Diesel | Gears | 6 | | Tail Lift | Column |
| Colour | WHITE | Doors | 2 | | | |
| VIN | XLRAEL1500L494926 | Brakes | Drum | | _ | |
| Tyres | | | | | | |
| NSF | NSI1 | NSI2 | | NSI3 | | NSI4 |
| OSF | OSI1 | OSI2 | | OSI3 | | OSI4 |
| Spare | NSO1 | NSO2 | | NSO3 | | NSO4 |
| | OS01 | OSO2 | | OSO3 | | OSO4 |

Features


| Cruise control | Radio/CD | Central locking | Cloth seat trim |
|----------------|----------|-----------------|-------------------------------------|
|----------------|----------|-----------------|-------------------------------------|

Photos





Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5

2: Door osf Dented Over 30mm





3: Qtr Panel osr Scratched UpTo 25mm Not Thru Paint 4: Tailgate Rusted Over 5mm

Interior

| Carpet Condition Seat Condition | Average Average | | Upholstery Condition Average Odour - | |
|------------------------------------|--------------------|----|--|----|
| Engine Runs | | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | | OK | No Excessive Smoking | OK |
| EML light illuminated | | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | | OK | DPF light illuminated | OK |
| ABS light illuminated | | OK | Service indicator light illuminated | OK |
| Windows | | OK | Radio | OK |
| | | | Steering | OK |