

VEHICLE INSPECTION REPORT

WO19HDZ

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 25/06/2019

VIN WDB9071352N046867

CAP Below £8,325.00

Year 2019

Body Style Luton L3

Gearbox MANUAL

Mileage 155,136 Miles
Warranted

MOT Due Expired

Axle Combi 4x2

Fuel Type Diesel

CAP Clean £11,850.00

Tail Lift Column

Colour WHITE

CAP Average £10,450.00

AD-BLUE, COLUMN TAIL LIFT, E/WINDOWS

Tyres

NSF

NSR

OSF

OSR


Spare

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Up To 25mm Thru Paint



2: Screen Front
Chipped
Over 10mm



3: Wing nsf
Dented
With Paint Damage



4: Door Moulding nsf
Broken
Replace



5: Door nsf
Dented
With Paint Damage



6: B Post ns
Hole
Over 10mm



7: Lamp osr
Broken
Replace



8: Door Mirror Assy osf
Broken
Replace



9: Carpets Front
Holed
Over 3mm

10: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	