

VEHICLE INSPECTION REPORT

RV70DFD

Iveco Eurocargo 75E16

| Inspection | | Vehicle | | | | | |
|-----------------|---------------------|--------------|-------------|-------------------|-----------------|--------|--|
| Serious Damage? | No | VAT Plus VAT | | | | | |
| | | V5 | Present | | | | |
| Details | | | | | | | |
| Reg. date | 22/10/2020 | VIN | ZCFA875B702 | ZCFA875B702700739 | | 4x2 | |
| Year | 2020 | Body Style | Box Van | | Rear Suspension | Steel | |
| Mileage | 88,420 Km Warranted | MOT Due | 30/11/2025 | | Rear Doors | Roller | |
| Fuel Type | Diesel | Cab Type | DAY CAB | | Tail Lift | Column | |
| Colour | WHITE | Gearbox | AUTOMATIC | | | | |
| Tyres | | | | | | | |
| NSF | NSI1 | NSI2 | | NSI3 | | NSI4 | |
| OSF | OSI1 | OSI2 | | OSI3 | | OSI4 | |
| Spare | NSO1 | NSO2 | NSO2 | | | NSO4 | |
| | OS01 | OSO2 | | OS03 | | OSO4 | |
| | | | | | | | |

Features

- Cruise control
 Cloth seat trim
- Radio/CD

- Air conditioning
- Front electric windows

Photos





















Condition Check



Damage Photos



1: Panel Front Scratched Over 25mm Not Thru Paint No Image

2: Bumper Front Cracked Over 25mm



3: Door Mirror Assy osf Broken Replace



4: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



5: Qtr Panel osr Scratched Over 25mm Not Thru Paint



6: Qtr Panel osr Scratched Over 25mm Thru Paint



7: Door osf Scratched Over 25mm Thru Paint



8: Door osf Scratched Over 25mm Thru Paint



9: Seat Base Cover nsf Soiled Heavy

Interior

| Carpet Condition Seat Condition | OK Poor | Upł Odd | nolstery Condition our | OK - | |
|---------------------------------|------------|------------|---------------------------|---------|----|
| Engine Runs | | OK No | o Excessive Smoking | | OK |
| EML light illuminated | | OK D | PF light illuminated | | OK |
| ABS light illuminated | | ОК | | | |