



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KW15BWV

Volvo FL 240

Non Runner

| Inspection | | Vehicle | |
|-----------------|----|---------|----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | Present |

| Details | | | | | |
|-----------|-------------|------------|-------------------|-----------------|-----------|
| Reg. date | 01/05/2015 | Colour | WHITE | Gearbox | AUTOMATIC |
| Year | 2015 | VIN | YV2T0W1A5FZ101925 | Axle Combi | 4x2 |
| Mileage | Not Showing | Body Style | Tilt & Slide | Rear Suspension | Air |
| Fuel Type | Diesel | Cab Type | CREW CAB | | |

NON-RUNNER, DOES NOT POWER UP MOT SHOWS 832,293KM 06/02/2025, ROGER DYSON TWIN DECK BODY, 2500KG UPPER BODY, 5000KG LOWER BODY, SPEC LIFT, WINCH




| Tyres | | | | |
|-------|------|------|------|------|
| NSF | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
| | OSO1 | OSO2 | OSO3 | OSO4 |

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
 Scratched
 Over 25mm Thru Paint

Interior

| Carpet Condition | - | Upholstery Condition | - |
|--------------------------|-------|--|-------|
| Seat Condition | - | Odour | - |
| Engine Runs | Fault | Gearbox 1st and Reverse Test | Fault |
| Brakes | Fault | Clutch Slip Test from Static | Fault |
| Turbo Boosting | Fault | Gearbox Static Gear Selection (engine running) | Fault |
| Parking Brake | Fault | No Excessive Smoking | Fault |
| EML light illuminated | Fault | Oil warning light illuminated | Fault |
| Airbag light illuminated | Fault | DPF light illuminated | Fault |
| ABS light illuminated | Fault | Service indicator light illuminated | Fault |