



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20XNR

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	03/08/2020	VIN	W1V9076352P255532	CAP Below	£3,850.00
Year	2020	Body Style	Panel Van L3	Gearbox	AUTOMATIC
Mileage	260,902 Miles Warranted	MOT Due	02/08/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£5,500.00		
Colour	WHITE	CAP Average	£4,775.00		

AD-BLUE, SIDE LOADING DOOR



Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Wing nsf
Dented
Over 30mm



3: Sill ns
Dented
Over 30mm

4: Sill ns
Dented
With Paint Damage



5: Door nsr
Dented
Over 30mm

6: Qtr Panel nsr
Dented
Over 30mm



7: Qtr Panel nsr
Dented
Over 30mm

8: Sill ns
Dented
Over 30mm



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Sill os
Dented
Over 30mm



11: Qtr Panel osr
Dented
Over 30mm

12: Sill os
Dented
Over 30mm



13: Sill os
Dented
Over 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK