

# VEHICLE INSPECTION REPORT

**WN12CGO**

## Mercedes-Benz Sprinter 513 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	30/03/2012	Colour	WHITE	Service documents	Electronic / Online
Year	2012	VIN	WDB9066532S671371	MOT Due	Expired
Mileage	200,250 Km Warranted	Body Style	Access Platform	Gearbox	MANUAL
Fuel Type	Diesel	Service history	Yes	Axle Combi	4x2

SIDE LOAD DOOR, VERSALIFT ET36NF (YEAR 2012), PLATFORM HEIGHT 12.9M

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim


## Photos












## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Over 30mm



2: Wing nsf  
Dented  
Over 30% Of Panel



3: Door nsf  
Dented  
Over 30mm



4: B Post ns  
Dented  
Over 30mm



5: Qtr Panel nsr  
Dented  
Over 30mm



6: Qtr Panel nsr  
Dented  
Over 30mm



7: Qtr Panel nsr  
Dented  
Over 30% Of Panel



8: Door osr  
Chipped  
Multiple Chips





9: Door osr  
Dented  
Over 30mm



10: Qtr Panel osr  
Dented  
Over 30mm



11: Qtr Panel osr  
Dented  
Over 30mm



12: Qtr Panel osr  
Dented  
Over 30mm



13: Qtr Panel osr  
Dented  
Over 30mm



14: Qtr Panel osr  
Dented  
Over 30mm



15: Qtr Panel osr  
Dented  
Over 30mm



16: Qtr Panel Moulding os  
Scuffed (Unpainted)  
Over 100mm



17: Qtr Panel osr  
Dented  
Over 30mm



18: Door Pad osf  
Soiled  
Heavy



19: Carpets Front  
Torn  
Over 10mm



20: Seat Base Cover osf  
Torn  
Over 3mm



21: Door Pad nsf  
Soiled  
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Poor		Poor	
Poor		-	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK