



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PF20JYJ

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details

Reg. date	24/08/2020	VIN	W1V9076352P256141	CAP Below	£5,000.00
Year	2020	Body Style	Panel Van L3	Gearbox	AUTOMATIC
Mileage	200,595 Miles Warranted	MOT Due	15/10/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£7,125.00		
Colour	WHITE	CAP Average	£6,225.00		

AD-BLUE, SIDE LOADING DOOR

Tyres




NSF
NSR
OSF
OSR
Spare

Features


- Rear parking sensor
- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing nsf
Dented
Over 30mm

2: Bumper Front
Insecure
Action Required



3: Door Mirror Assy nsf
Broken
Replace

4: D Post ns
Chipped
Over 5mm



5: Sill ns
Dented
Over 30mm

6: Sill ns
Dented
Over 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Sill Panel Trim os
Missing
Replace



11: Sill os
Dented
Over 30mm

12: Sill os
Dented
Over 30mm



13: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK