



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PO13ECJ

Daf LF 45.140

| Inspection | | Vehicle | |
|-----------------|----|---------|----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | Present |

| Details | | | |
|-----------|------------|-------------------|-------------------|
| Reg. date | 09/04/2013 | VIN | XLRAE45FF0L425358 |
| Year | 2013 | Body Style | Box Van |
| Mileage | TBC | Service history | Yes |
| Fuel Type | Diesel | Service documents | Printout |
| Colour | RED | MOT Due | Expired |
| | | Gearbox | MANUAL |
| | | Axle Combi | 4x2 |
| | | Rear Suspension | Steel |
| | | Tail Lift | Cantilever |

COLLECTED AS NON-RUNNER, CAB CORROSION, TAIL LIFT PLATFORMS, FAULTS NEED ATTENDTION, WARNING LIGHTS ON DASH



| Tyres | | | | |
|-------|------|------|------|------|
| NSF | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
| | OSO1 | OSO2 | OSO3 | OSO4 |

Features


- Radio/CD

Photos





Condition Check




Damage Photos



1: Sill os
Rusted
Over 5mm

2: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
Multiple Chips

4: Wing osf
Scratched
Over 25mm Not Thru Paint



5: Door osf
Dented
With Paint Damage

6: Qtr Panel osr
Rusted
Over 5mm



7: Tailgate
Rusted
Over 5mm

8: Qtr Panel nsr
Rusted
Over 5mm



9: Door Moulding nsf
 Scuffed (Unpainted)
 Over 100mm

Interior

| Carpet Condition | - | Upholstery Condition | - |
|--------------------------|-------|--|----|
| Seat Condition | - | Odour | - |
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | Fault | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| | | Steering | OK |