



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE63NVG

Daf LF 55.220

| Inspection | | Vehicle | |
|-----------------|----|---------|----------|
| Serious Damage? | No | VAT | Plus VAT |
| | | V5 | Present |

Details

| | | | | | |
|-----------|----------------------|------------|-------------------|-----------------|------------|
| Reg. date | 01/12/2013 | VIN | XLRAE55GF0L433838 | Axle Combi | 4x2 |
| Year | 2013 | Body Style | Box Van | Rear Suspension | Steel |
| Mileage | 875,145 Km Warranted | MOT Due | 31/07/2026 | Tail Lift | Cantilever |
| Fuel Type | DIESEL | Cab Type | DAY CAB | | |
| Colour | RED | Gearbox | AUTO | | |

COLLECTED AS NON-RUNNER, FLOOR, REAR AXLE & TAIL LIFT REQUIRE ATTENTION


Tyres




| | | | | |
|-------|------|------|------|------|
| NSF | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
| | OSO1 | OSO2 | OSO3 | OSO4 |

Features


- Cruise control
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Cracked
Over 25mm



3: Moulding nsf Wing
 Scratched (Painted)
 Over 25mm Thru Paint

4: Door nsf
 Scratched
 Over 25mm Thru Paint



5: Wing Front Arch Extension ns
 Scratched (Painted)
 Over 25mm Thru Paint

6: Qtr Panel osr
 Cracked
 Replace



7: Door nsf
 Scratched
 Over 25mm Thru Paint

8: Moulding osf Wing
 Scratched (Painted)
 Over 25mm Thru Paint



9: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

10: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition Poor
Seat Condition OK

Upholstery Condition OK
Odour -

| | | | |
|-----------------------|----|-----------------------|----|
| Engine Runs | OK | No Excessive Smoking | OK |
| Turbo Boosting | OK | | |
| EML light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | | |