



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ20ZYU

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	31/07/2020	Colour	WHITE	CAP Average	£7,725.00
Year	2020	VIN	W1V9076352P255557	CAP Below	£6,175.00
Mileage	134,206 Miles Warranted	Body Style	Panel Van L3	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	16/03/2027	Gears	6
GVW	3500kg	CAP Clean	£8,800.00		


WARNING LIGHT ON DASH AD-BLUE, SIDE LOADING DOOR



Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Rear parking sensor
- Front electric windows

Photos







Condition Check





Damage Photos





1: Wing of front door
Dented
With Paint Damage

2: Bumper Front
Cracked
Over 25mm





3: Bonnet
Chipped
Multiple Chips

4: Screen Front
Chipped
Up To 10mm




5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm


6: Door nsf
Dented
Over 30% Of Panel



7: Door nsr
Scratched
Over 25mm Not Thru Paint





8: Door nsr
Dented
With Paint Damage





9: Qtr Panel nsr
Dented
With Paint Damage

10: Qtr Panel nsr
Dented
With Paint Damage





11: Qtr Panel Trim ns
Scuffed
Over 25mm

12: Qtr Panel nsr
Dented
With Paint Damage




13: Door Moulding nsr
Broken
Replace

14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Door nsr
Scratched
Over 25mm Thru Paint





16: Door nsr
Dented
Between 10mm + 30mm




17: Badgedecal Rear
Missing
Replace


18: Door osr
Dented
With Paint Damage



19: Qtr Panel osr
Dented
With Paint Damage





20: Qtr Panel osr
Dented
With Paint Damage





21: Qtr Panel osr
Dented
With Paint Damage

22: Bumper Rear Moulding
Broken
Replace





23: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

24: Qtr Panel osr
Dented
With Paint Damage




25: Qtr Panel osr
Dented
With Paint Damage

26: Qtr Panel osr
Dented
With Paint Damage



27: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



28: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

29: Seat Base Cover osf
Holed
Over 3mm

Interior

**Carpet Condition
Seat Condition**

Average
Average

**Upholstery Condition
Odour**

Average
No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK