



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DE19WUM

Isuzu N75 190

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details			
Reg. date	18/03/2019	VIN	JAANPR75MJ7100485
Year	2019	Body Style	Dropside
Mileage	73,377 Km Warranted	MOT Due	28/02/2027
Fuel Type	Diesel	Cab Type	DAY CAB
Colour	BLUE/YELLOW	Gearbox	AUTOMATIC
		Axle Combi	4x2
		Rear Suspension	Steel
		Tail Lift	Cantilever

TAIL LIFT IN-OP SERVICE SCHEDULE LIST AVAILABLE, SURROUND CAMERA SYSTEM



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera

Photos






ISUZU MOTORS LTD.
 e4*2007/46*0324
 JAANPR75MJ7100485
 GVW 7500 Kg
 GCW 11000 Kg
 AXLE 1 3100 Kg
 AXLE 2 6000 Kg
 P.NO.8981893111



PPS
 TELEPHONE 0161 767 9854
 LENGTH 758 mm
 HEIGHT 296 mm
 WIDTH 241 mm
 BODY No. 43173



Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint

2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Headlamps
Broken
Replace



5: Door nsf
Dented
With Paint Damage

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Chipped
Edge Chip

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Door osf
Scratched
Over 25mm Not Thru Paint



11: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

12: Door osf
Dented
With Paint Damage



13: Door osf
Chipped
Edge Chip

14: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK