

VEHICLE INSPECTION REPORT

BJ19ZWG

Iveco Eurocargo 120-210

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	29/03/2019	Colour	WHITE	Gearbox	MANUAL
Year	2019	VIN	ZCFAG1EF202690303	Axle Combi	4x2
Mileage	50,170 Km Warranted	Body Style	Pole Erection Unit	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/07/2026		
GVW	12000kg	Cab Type	DAY CAB		

HMF A10 REMOTE CRANE (2018), AUGER TORQUE HOLE BORER ATTACHMENT

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Switches And Controls
Broken
Replace



2: Fascia Trim
Missing
Replace



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front Moulding
Missing
Replace



5: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Panel Rear
Cracked
Replace



8: Door osf
Scratched
Over 25mm Thru Paint





9: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint

10: Door osf
Scratched
Over 25mm Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint

12: A Post os
Cracked
Replace



13: Bumper Front
Cracked
Over 25mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		