



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ66BFU

Daf LF 150

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details


Reg. date	01/11/2016	VIN	XLRAEL1500L459382	Axle Combi	4x2
Year	2016	Body Style	Box Van	Rear Suspension	Steel
Mileage	944,349 Km Warranted	MOT Due	30/04/2026	Tail Lift	Cantilever
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	RED	Gearbox	MANUAL		




COLLECTED AS NON-RUNNER, CORROSION, REAR AXLE REQUIRES ATTENTION

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Holed
Over 3mm

2: Carpets Front
Holed
Over 3mm



3: Fascia Trim
Damaged
Replace

4: Screen Front
Cracked
Replace



5: Bonnet
Chipped
Multiple Chips

6: Bumper Front
Scratched
Over 100mm Thru Paint



7: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint

8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsf
Scratched
UpTo 25mm Not Thru Paint

10: Door nsf
Dented
With Paint Damage



11: Door osf
Scratched
Over 25mm Thru Paint

12: Door osf
Dented
Between 10mm + 30mm



13: Door osf
Dented
With Paint Damage

14: Door osf
Dented
With Paint Damage



15: Door osf
 Scratched
 Over 25mm Thru Paint

16: Moulding osf Wing
 Scratched (Painted)
 Over 25mm Thru Paint



17: Door Moulding nsf
 Broken
 Replace

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		