

# VEHICLE INSPECTION REPORT

**BF23YOM**

## Iveco Eurocargo 120-210

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

|           |                     |            |                    |                 |         |
|-----------|---------------------|------------|--------------------|-----------------|---------|
| Location  | Livingston          | GVW        | 12000kg            | Cab Type        | DAY CAB |
| Reg. date | 26/05/2023          | Colour     | WHITE              | Gearbox         | MANUAL  |
| Year      | 2023                | VIN        | ZCFAH1EF302728957  | Axle Combi      | 4x2     |
| Mileage   | 67,243 Km Warranted | Body Style | Pole Erection Unit | Rear Suspension | Steel   |
| Fuel Type | Diesel              | MOT Due    | Expired            |                 |         |

PALFINGER PK 9.501 REMOTE CRANE (YEAR 2022), AUTOGUIDE 40PXV AUGER (YEAR 2023), POLE JACK, HEATED DRYING LOCKER, 240V POWER, AUGER EXTENSION POLE, SURROUND CAMERA SYSTEM

### Tyres

|       |      |      |      |      |
|-------|------|------|------|------|
| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |

## Features

- Radio/CD
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Door Moulding of  
Scuffed (Unpainted)  
Over 100mm

2: Door of  
Dented  
Over 30mm



3: Door nsf  
Dented  
With Paint Damage

4: Door Moulding nsf  
Scuffed (Unpainted)  
Over 100mm

Interior

| Carpet Condition         |  | Average |  | Upholstery Condition                           |  | Average |  |
|--------------------------|--|---------|--|------------------------------------------------|--|---------|--|
| Seat Condition           |  | Average |  | Odour                                          |  | -       |  |
| Engine Runs              |  | OK      |  | Gearbox 1st and Reverse Test                   |  | OK      |  |
| Brakes                   |  | OK      |  | Clutch Slip Test from Static                   |  | OK      |  |
| Turbo Boosting           |  | OK      |  | Gearbox Static Gear Selection (engine running) |  | OK      |  |
| Parking Brake            |  | OK      |  | No Excessive Smoking                           |  | OK      |  |
| EML light illuminated    |  | OK      |  | Oil warning light illuminated                  |  | OK      |  |
| Airbag light illuminated |  | OK      |  | DPF light illuminated                          |  | OK      |  |
| ABS light illuminated    |  | OK      |  | Service indicator light illuminated            |  | OK      |  |
| Windows                  |  | OK      |  | Radio                                          |  | OK      |  |
|                          |  |         |  | Steering                                       |  | OK      |  |