

VEHICLE INSPECTION REPORT

BF23YOL

Iveco Eurocargo 120-210

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Avonmouth

Reg. date 22/05/2023

Year 2023

Mileage 28,520 Km Warranted

Fuel Type Diesel

GVW 12000kg

Colour WHITE

VIN ZCFAH1EF202729386

Body Style Pole Erection Unit

MOT Due 30/11/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHT ON DASH, PALFINGER PK 9.501 REMOTE CRANE (2022), AUTOGUIDE 40PXV AUGER (YEAR 2022), POLE JACK, HEATED DRYER LOCKER, 240V POWER, AUGER EXTENSION POLE, REAR VIEW CAMERA

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

NSI2

OSI2

NSO2

OSO1

OSO2

NSI3

OSI3

NSO3

OSO3

NSI4

OSI4

NSO4




OSO4







Features

- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim

Photos










Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Multiple Chips



3: Moulding nsf Wing
Scratched (Painted)
UpTo 25mm Thru Paint

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace

6: Wing nsf
Cracked
Replace



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Qtr Panel nsr
Chipped
Multiple Chips

10: Door osf
Chipped
Multiple Chips

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		