



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PF20ACO**

## Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details					
Reg. date	31/07/2020	VIN	W1V9076352P255553	CAP Below	£6,050.00
Year	2020	Body Style	Panel Van L3	Gearbox	AUTOMATIC
Mileage	140,979 Miles Warranted	MOT Due	25/03/2027	Gears	6
Fuel Type	Diesel	CAP Clean	£8,625.00		
Colour	WHITE	CAP Average	£7,575.00		

AD BLUE, SIDE LOADING DOOR



Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

## Features


- Rear parking sensor
- Front electric windows

## Photos





## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



2: Wing of  
Scratched  
Over 25mm Thru Paint



3: Bonnet  
Chipped  
Multiple Chips

4: Screen Front  
Chipped  
UpTo 10mm



5: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm

6: Wing nsf  
Dented  
With Paint Damage



7: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm

8: Door nsf  
Scratched  
Over 25mm Not Thru Paint



9: Door nsf  
Dented  
Over 30mm

10: B Post ns  
Dented  
With Paint Damage



11: Door nsr  
Dented  
With Paint Damage

12: Door nsr  
Dented  
Over 30mm



13: Door nsr  
Scratched  
Over 25mm Thru Paint

14: Qtr Panel nsr  
Dented  
With Paint Damage



15: Sill ns  
Dented  
With Paint Damage



16: Qtr Panel nsr  
Dented  
With Paint Damage




17: Sill ns  
Dented  
With Paint Damage



18: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



19: Bumper Rear Moulding  
Missing  
Replace



20: Qtr Panel nsr  
Dented  
With Paint Damage




21: Door nsr  
Dented  
Over 30mm

22: Roof  
Dented  
Over 30mm



23: Door nsr  
Dented  
With Paint Damage

24: Badgedecal Rear  
Missing  
Replace



25: Door osr  
Dented  
With Paint Damage

26: Qtr Panel osr  
Dented  
With Paint Damage



27: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

28: Qtr Panel osr  
Dented  
With Paint Damage



29: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

30: Qtr Panel osr  
Dented  
With Paint Damage



31: Qtr Panel osr  
Dented  
With Paint Damage

32: Carpets Front  
Holed  
Over 3mm



33: Steering Wheel  
 Damaged  
 Replace

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK