

VEHICLE INSPECTION REPORT

PJ20NFG

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 22/07/2020

Year 2020

Mileage 154,480 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P252416

Body Style Panel Van L3

MOT Due 25/07/2025

CAP Clean £7,500.00

CAP Average £6,725.00

CAP Below £5,525.00

Gearbox AUTOMATIC

DELAY IN PARKING BRAKE AD-BLUE, SIDE LOAD DOOR, BEEN ON FULL R&M CONTRACT FROM NEW

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Dented
Over 30mm



3: Qtr Panel nsr
Dented
Over 30mm



4: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



6: Qtr Panel nsr
Dented
Over 30mm



7: C Post ns
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Dented
Over 30mm



9: Door nsr
Dented
Over 30mm



10: Door osr
Dented
Over 30mm



11: Unclassified
Substantial Accident Damage
Report Only



12: Wing osf
Dented
Over 30% Of Panel

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK