



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**YT09BKA**

## Scania N 230

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

### Details

Reg. date	06/05/2009	Colour	RED	Cab Type	DAY CAB
Year	2009	VIN	SZAN4X20001864294	Gearbox	AUTOMATIC
Mileage	817,288 Miles Not Warranted	Body Style	Double Deck Bus	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	20/01/2027	Rear Suspension	Air

\*5% BUYERS FEE\*\*MOT RECORDED IN A MIX OF KM & MILES, WARNING LIGHT ON DASH\* OMNICITY BODY, 77 SEATS


### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Park assist camera
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Screen Front  
Cracked  
Replace

2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Bonnet  
Chipped  
Multiple Chips



4: A Post ns  
Scratched  
Over 25mm Thru Paint




5: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint




6: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel Moulding ns  
Scratched (Painted)  
Over 25mm Thru Paint





9: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

10: Qtr Panel Moulding ns  
Scratched (Painted)  
Over 25mm Thru Paint



11: C Post ns  
Scratched  
Over 25mm Thru Paint

12: Panel Rear  
Scratched  
Over 25mm Thru Paint



13: Bumper Rear Moulding  
Broken  
Replace

14: Bumper Rear  
Cracked  
Over 25mm



15: C Post os  
Scratched  
Over 25mm Thru Paint

16: Qtr Panel Moulding os  
Scratched (Painted)  
Over 25mm Thru Paint



17: Qtr Panel Moulding os  
Scratched (Painted)  
Over 25mm Thru Paint

18: Door osr  
Scratched  
Over 25mm Thru Paint



19: Qtr Panel Moulding os  
Scratched (Painted)  
Over 25mm Thru Paint

20: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



21: Qtr Panel Moulding os Scratched (Painted) Over 25mm Thru Paint

22: Aperture Seal osf Broken Replace



23: Aperture Seal osf Missing Replace

24: Aperture Seal osf Broken Replace



25: Screen Front Cracked Replace

26: Dash Warning Lights Displayed No Action

**Interior**

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	OK	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault		