

VEHICLE INSPECTION REPORT

SL12CDU

Volkswagen Crafter CR35 2.0 TDI 109PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/03/2012

Year 2012

Mileage 77,430 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WV1ZZZ2E2C6036262

Body Style Crew Van

MOT Due Expired

CAP Clean £2,775.00

CAP Average £2,175.00

CAP Below £1,425.00

Gearbox MANUAL

Gears 6

Doors 2

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos







Condition Check



Damage Photos



1: Seat Base Cover nsf
Torn
Over 3mm



2: Seat Base Cover osf
Torn
Over 3mm



3:



4: Sill os
Rusted
Over 5mm



5:



6: Bonnet
Dented
Over 30mm



7: Wing osf
Rusted
Over 5mm



8: Door osf
Dented
Over 30mm



9: Qtr Panel osr
Rusted
Over 5mm



10: Tailgate
Dented
Over 30mm



11: Badgedecal Rear
Missing
Replace



12: Qtr Panel nsr
Rusted
Over 5mm



13: Sill ns
Rusted
Over 5mm



14: Door Mirror Glass ns
Missing
Replace



15: Door Mirror Glass ns
Missing
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Poor	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		