

VEHICLE INSPECTION REPORT

HX72YKW

Mercedes-Benz Atego 1223

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details

Location	Livingston	GVW	11990kg	Cab Type	DAY CAB
Reg. date	06/02/2023	Colour	WHITE	Gearbox	AUTOMATIC
Year	2023	VIN	W1T96700520628855	Axle Combi	4x2
Mileage	56,145 Km Warranted	Body Style	Pole Erection Unit	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	Expired		



PALFINGER PK 9.501 REMOTE CRANE (YEAR 2022), AUTOGUIDE 40PXV AUGER, POLE JACK, HEATED DRYING LOCKER, 240V POWER, AUGER EXTENSION POLE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos







Condition Check



Damage Photos



1: Door Moulding of
Scuffed (Unpainted)
Over 100mm

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Door osf
Dented
Over 30mm

4: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Turbo Boosting		OK		Gearbox Static Gear Selection (engine running)		OK	
Parking Brake		OK		No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	
Windows		OK		Radio		OK	
				Steering		OK	