

VEHICLE INSPECTION REPORT

WP65FHA

Mercedes-Benz ACTROS 1824

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/12/2015

VIN WDB96300320025116

Gearbox AUTOMATIC

Year 2015

Body Style Curtainside

Axle Combi 4x2

Mileage 431,929 Km Not Warranted

Service history Yes

Rear Suspension Steel

MOT Due 31/12/2025

Rear Doors Barn

Fuel Type Diesel

Cab Type CLASSICSPACE CAB

Tail Lift Tuckaway

Colour BLUE

SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Moulding on Wing
Scratched (Painted)
Over 25mm Thru Paint



2: Bumper Front
Hole
Over 25mm



3: Screen Front
Chipped
Over 10mm



4: Screen Front
Chipped
Over 10mm



5: Screen Front
Chipped
Over 10mm



6: Bonnet
Chipped
Multiple Chips



7: General Exterior
Soiled
Light



8: Door Mirror Assy nsf
Broken
Replace



9: General Exterior
Soiled
Light



10: General Exterior
Soiled
Light



11: Door nsr
Cracked
Replace



12: General Exterior
Soiled
Light



13: General Exterior
Soiled
Light



14: General Exterior
Soiled
Light



15: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Average	
Average		-	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK