

# **VEHICLE INSPECTION REPORT**

Vehicle

LN19YPF

### **Mercedes-Benz ACTROS 1827**

Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	01/07/2019	VIN	WDB96300320343643	Gearbox	AUTOMATIC
Year	2019	Body Style	Curtainside	Axle Combi	4x2
Mileage	335,792 Km Not Warranted	Service history	Yes	Rear Suspension	Steel
		MOT Due	31/07/2025	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	STREAMSPACE CAB (2.3M, 320MM)	Tail Lift	Tuckaway
Colour	BLUE	••			

#### SURROUND CAMERA SYSTEM

Tyres
-------

Inspection

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	_
	OS01	OSO2	OSO3	OSO4	

### **Features**

Air conditioning

#### **Photos**
















# **Condition Check**



## **Damage Photos**



1: Bumper Front Scratched Over 100mm Thru Paint



2: Bumper Front Scratched Over 100mm Thru Paint



3: General Exterior Soiled Light



4: General Exterior Soiled Light



5: General Exterior Soiled Light

#### Interior

Carpet Condition Seat Condition	Average OK		Upholstery Condition Odour	OK -	
Engine Runs		OK	Gearbox 1st and Reverse	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	tic	OK
Parking Brake		OK	Gearbox Static Gear Sele	ection (engine running)	OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminat	ed	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	minated	OK