



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LD18BVX

Ford Transit Custom 320 2.0 TDCi 105ps

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	18/05/2018	Colour	WHITE
Year	2018	VIN	WF0YXXTTGYJS38969
Mileage	91,701 Miles Warranted	Body Style	Panel Van L1
Fuel Type	Diesel	Service history	Yes
GVW	3200kg	MOT Due	Expired
		CAP Clean	£6,350.00
		CAP Average	£5,350.00
		CAP Below	£4,050.00
		Gearbox	MANUAL
		Gears	6


WARNING LIGHTS ON DASH TWIN SIDE LOAD DOOR, E/MIRRORS, AD-BLUE


Tyres
NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Roof
Chipped
Multiple Chips

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Dented
Over 30mm

6: Door nsf
Dented
With Paint Damage



7: Door nsf
Scratched
Over 25mm Thru Paint

8: Door nsf
Dented
With Paint Damage





9: Door nsf
Dented
With Paint Damage

10: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

12: Qtr Panel nsr
Dented
With Paint Damage



13: Qtr Panel nsr
Dented
With Paint Damage

14: Door nsr
Dented
With Paint Damage



15: Qtr Panel osr
Dented
Over 30mm

16: Qtr Panel osr
Dented
Over 30mm



17: Door osf
Scratched
Over 25mm Not Thru Paint

18: Bonnet
Dented
Over 30mm



19: Bonnet
Dented
Over 30mm

20: Carpets Front
Holed
Over 3mm



21: Seat Base Cover osf
Holed
Over 3mm

22: Door Pad osf
Scuffed
Over 25mm



23: Seat Base Cover nsf
Soiled
Heavy

24: Door Pad nsf
Soiled
Heavy



25: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		