



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

RV70DCO

Iveco Eurocargo 75-160

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow

Details			
Reg. date	22/10/2020	VIN	ZCFA875B602700750
Year	2020	Body Style	Box Van
Mileage	117,926 Km Warranted	MOT Due	31/10/2026
Fuel Type	Diesel	Cab Type	DAY CAB
Colour	WHITE	Gearbox	AUTOMATIC
		Axle Combi	4x2
		Rear Suspension	Steel
		Rear Doors	Roller
		Tail Lift	Column

WARNING LIGHT ON DASH




Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Air conditioning
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action



2: Carpets Front
Holed
Over 3mm



3: Screen Front
Chipped
Over 10mm

4: Bonnet
Chipped
Multiple Chips



5: Moulding nsf Wing
Scratched (Painted)
UpTo 25mm Thru Paint

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Cracked
Replace



9: Qtr Panel osr
Cracked
Replace

10: Qtr Panel osr
Cracked
Replace



11: Door osf
Chipped
Multiple Chips

12: Door osf
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

14: Roof
Scratched
Over 25mm Thru Paint



15: Moulding of Wing
 Scratched (Painted)
 Over 25mm Thru Paint

16: Moulding of Wing
 Scratched (Painted)
 Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition OK

Upholstery Condition OK
Odour -

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		